


Model: HCD-S300, DAV-S300**No.** **667****Subject:** Incompatibility between the new and old DVD
& PW-932 boards**Date:** May 22, 2001**Situation:**
(X18Z)

There is a compatibility problem between the new and former types of DVD BOARD and PW-932 BOARD. The POWER LED will light orange if this combination is used.


Solution:

Take the following action when using a new DVD BOARD or PW-932 BOARD in combination with an old board.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
NA	DVD BOARD	1-676-634-1X	DVD BOARD	1-676-634-2X
NA	PW-932 BOARD	1-676-640-1X	PW-932 BOARD	1-676-945-1X




Repair method when using new DVD BOARD with old PW-932 BOARD.



Repair method when using a new PW-932 BOARD with an old DVD BOARD.

- a) Connect a wire lead between CN015 pin 4 to IC905 pin 1 on the A side of the old DVD board. (see diagram)



- b) Remove R936 on the B side of the old DVD board.

