

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-U70/U300/U300RF/U303/
U303RF/U404/U606

No. 347

Subject: Sound Skip, Or Disc Does Not Play.

Date: December 27, 1994

Symptom:
(57)

The disc skips (may often only be heard as a very brief "tick" sound), or the disc does not play. The complaint may be that these problems only occur when certain discs are played; these discs may be somewhat thinner than discs which do not exhibit the problems.

Solution:

Determine if the problem is caused by thin discs, by playing the Changer Test Disc (specially manufactured "thin" disc). The changer should be able to play this disc (both vertically and horizontally) without skipping.

If the discs skips, replace the Chuck Plate. If the disc still skips, replace the OMD Chassis also.

| REF | DESCRIPTION | PART NUMBER |
|-----|-------------------|--------------|
| - | CHANGER TEST DISC | J-2502-012-0 |
| 166 | CHUCK PLATE | 3-380-759-02 |
| 261 | OMD CHASSIS | X-2625-270-1 |



