

**Model:** KV-27FV16**No. 518****Subject:** SRS Mis-Operation**Date:** January 12, 2001**Symptom:**

**(117X)** When the SRS is activated, and the set is turned off, one would expect SRS to be activated when the set is turned back on. In reality, when the set is turned on the SRS is deactivated, but the customer menu screen shows that the SRS is still activated, when it is not.

**Solution:** If the customer complains of the symptom above please replace the CPU IC001 on the MA Board with version 3.1.

Reference	Former	New	Part Number
IC001	M37280MK-11SP	M37280EKSP Version 3.1	T-998-607-66