

Model: KP-43HT20, KP-53HS20, KP-53HS30**No. 543****Subject:** ABL Flicker in picture**Date:** August 3, 2001**Symptom:**
(1185)

ABL flicker may be seen in the picture on the models above when 16:9 enhanced mode is turned on. The KP-61HS20 & KP-61HS30 were corrected before release. Therefore no action is necessary on the 61-inch models.

Solution: To correct this flicker the procedure below should be followed:

Model	Serial number Range of units affected
KP-43HT20	9700001-9703060
KP-53HS20	9700001-9701900
KP-53HS30	9700001-9703010

Procedure for Data Change on RA-6 Models

1. Access service mode during power on: (Press "**Display**", "**5**", "**Volume Up**", "**Power**".)
2. Exit auto channel program: (Press "**Channel** – ")
3. Select Video 1
4. Change display mode to 16:9 Enhanced Mode using the menu:
 - A. Press "Menu"
 - B. Use the joystick to select "Setup" settings
 - C. Select "16:9 Enhanced: Auto"
 - D. Change the setting to "ON"
5. Change the data for ABLT, from 15 to 0 by
 - A. Press "**2**" (7) times.

- B. Press **"4"** (8) times (ABLT is displayed).
- C. Press **"6"** (15) times (changes data from 15 to 0).
- D. Press **mute, enter** (Verify green **"WRITE"** turns red **"WRITE"**).
- 6. Press **"0", enter** to confirm data is 0.

If adjusting Sales Stock then the following steps should be included:

- 1. Perform "test-reset" by pressing **"8"** and **"ENTER"**.
- 2. Confirm channel 6 appears in snow signal.
- 3. Turn set off by power button (not by pulling AC cord from socket).
- 4. Repackage the set.