

**Model:** KP-41T15, KP-46S15, KP-53S15**No.** 527**Subject:** Supplement-2 CRT part numbers are incorrect**Date:** March 16, 2001**Symptom:**  
(1185)

The part numbers given in Supplement-2 for the CRT's are incorrect.

**Solution:**

Please see the table below for the correct CRT part numbers.

**SUPPLEMENT-2****SUBJECT: ADD OF PART No.** : Indicates changed portion



File this supplement with the Supplement and Service manual.

**SECTION 2. DISASSEMBLY****2-12. PICTURE TUBE REMOVAL(See page19 )**

## &lt; Note &gt;

*As the picture tube was changed from the short one to the long one, the main bracket on the primary production sets needs to be cut as shown in the picture.*

*Other wise the CRT cannot be assembled.*



Please cut the plastic chassis with cutters so the CRT can fit properly

**BRACKET,MAIN PC  
BOARD  
(Part No.4-047-949-03)**

See CRT P/N information on the next page.

<b>Model</b>	<b>Description</b>	<b>Incorrect</b>	<b>Correct</b>	<b>Subbed to</b>
KP-41T15	CRT Red	8-733-496-01	8-736-080-05	8-733-578-25
	CRT Green	8-733-494-01	8-736-078-05	8-733-577-25
	CRT Blue	8-733-495-01	8-736-079-05	8-733-574-15
KP-46S15	CRT Red	8-733-496-01	8-736-080-05	8-733-578-25
	CRT Green	8-733-494-01	8-736-078-05	8-733-577-25
	CRT Blue	8-733-495-01	8-736-079-05	8-733-574-15
KP-53S15	CRT Red	8-733-498-01	8-736-082-05	8-733-579-25
	CRT Green	8-733-497-01	8-736-078-05	8-733-577-25
	CRT Blue		8-736-081-05	8-733-575-15