

SONY

Video/RGB Monitor Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: GVM2000, GVM2100, GVM2020

No. 1


Subject: Q3504 and Q3507 Protection From Over Voltage

Date: March 12, 1993


Symptom:
(111) No Picture.

Solution: Check Q3504 (H. Out) and Q3507 (Converter. Out) for shorts. If shorted, perform the following to prevent possible re-occurrence.

SOLDER DIODE 1SS119
PARALLEL TO R1510 ON A-BOARD



A-BOARD
SOLDER SIDE



Reference: DP92-0051



PRINTED IN U.S.A.
CSI-112293-1

CSI-112 GVM Monitors