

1989 issue, I noted some errors in the "Early-Warning Intrusion Alarm" article. In Fig. 1, the designations for pins 3 and 7 for IC2 are reversed, and pin 8 is not shown going to the +5-volt rail. It also appears that the article was cut short after page 27 because on page 25 a reference is made to Fig. 8, which appears nowhere in the article.

Scott McAlpine  
Renton, WA

*Thanks for pointing out the schematic errors. Reference to Fig. 8 in the article is a typographical error, it should read Fig. 7.—Ed.*