

CORRECTION

I was extremely pleased to see my article, "Instrument Landing Systems," in the March 1984 issue of your magazine. I would like to point out one correction, however.

On page 52, fourth line from the bottom of the first column, the text reads: "feet in width at the outer marker or 3°."



In the original manuscript, that line read: "feet in width at the landing threshold or 3°."

That makes quite a difference in the structure of the radiated signal, and may cause some of our technicians to write in for clarification.

Thanks again for publishing my article, and I hope to send you another one soon.

BILL SEWELL
Schaumburg, IL