

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-350/550

No. 1

Subject: Disc Table Continuously Loads

Date: January 27, 1988

Symptom:
(262)

Disc table continuously loads.

Solution:

Replace loading belt with new type listed below:

Ref. No.	Description	Part Number	
		Former	New
123	Belt	4-917-522-01	4-917-522-02

CSA-13 Contact Disc

Reference:

PRINTED IN U.S.A.
CSA-13188-1