

SONY

Dictation Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: M-2000

No. 10


Subject: "Play" Pedal Breaks

Date: February 19, 1992

Symptom:
(63) The posts on the "play" pedal may break with heavy usage.

Solution: If the above symptom occurs, replace the pedal case along with the pedal. The improved case helps to prevent pedal breakage.

REFERENCE NUMBER	DESCRIPTION	PART NUMBER
102	PEDAL (RIGHT)	2-263-525-11
105	CASE	2-263-526-01



Reference: FPR-M1024

PRINTED IN U.S.A.
CSA-15292-1

CSA-15
Personals