

**SONY.**

## Dictation Products Service Bulletin

**Sony Service Company** - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** BM-77/88/880, CCP-200RF/D

**No. 20**

**Subject:** Semiconductor Fuse List

**Date:** February 5, 1993

**Symptom:**  
(\*\*)

**Semiconductor Fuse (Link, IC)**

| RATING (A) | PART NUMBER  | ICP NUMBER | FIGURE | MODEL USED  |
|------------|--------------|------------|--------|-------------|
| 0.25       | 1-532-727-11 | N5         | A      | ---         |
| 0.4        | 1-532-605-00 | N10        | A      | CCP-200RF/D |
| 0.6        | 1-532-679-00 | N15        | A      | CCP-200RF/D |
| 0.8        | 1-532-685-00 | N20        | A      | ---         |
| 1.0        | 1-532-637-00 | N25        | A      | ---         |
| 1.25       | 1-532-907-11 | N31        | A      | ---         |
| 1.5        | 1-532-675-21 | N38        | A      | BM-88/880   |
| 2.7        | 1-532-686-21 | N75        | A      | ---         |
| 1.5        | 1-532-675-00 | F38        | B      | BM-77       |

Dictation  
CSA-15




FIG. A




FIG. B

**NOTE:** The ICP No. X 40 = The approximate rating in milliamperes.