

SONY

Dictation Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: BM-530

No.18

Subject: IC-101 Replacement

Date: October 16, 1992

Symptom:
(**)

The original IC is no longer available.

Solution:

Please use the following replacement IC for BM-530:

PART DESCRIPTION	ORIGINAL PART NUMBER	REPLACEMENT PART NUMBER
CX20107	1-807-510-21	8-759-927-71

NOTE 1: Since the replacement IC has straight leads, it is necessary to form all the leads to resemble the original IC.

NOTE 2: CX20107, P/N 8-752-010-71 can not be used for BM-530, because of the chip mount type short leads.

Dictation
CSA-15

Reference: YK

PRINTED IN U.S.A.
CSA-151092-2