

---

**Model:** KV-27FV15, KV-27FV27, KV-32FS10, KV-32FV1  
KV-32FV15, KV-32FV16, KV-32FV26  
KV-32XBR200, KV-32XBR250, KV-36FS10  
KV-36FS12, KV-36FS13, KV-36FS16  
KV-36FS17, KV-36FV1, KV-36FV15, KV-36FV16  
KV-36FV26, KV-36FV27, KV-36XBR200  
KV-36XBR250

**No. 540**

**Subject:** Part Number Correction (HDT)

**Date:** July 30, 2001

**Symptom:**  
**(xxxx)**

The service Manual lists the incorrect part number for Ref T501 the Horizontal Drive Transformer (HDT).

**Solution:**

Please correct the part number in your Service Manual as listed below:  
Chassis affected AA-2H, AA-2W, AA-2U

Ref	Incorrect P/N	Correct P/N
T501	1-437-195-11	1-437-195-31