


3-4-92

MB-1 Improvement Modifications

There is only 1 Component Added to The MB-1. A 4.3K $\frac{1}{4}$ w. resistor needs To be Tacked Between R150 & C92 a. Shown. Alternately, The new Resistor is connected in Parallel w C92. This component is called R170.



<http://www.adadepot.com>

