

4-25-85

S-1000 TEST POINT LIST

- TEST POINT # 1 NOT USED
- 2 INPUT SIGNAL
  - 3 SIGNAL IN TO A/D CONVERTOR
  - 4 ENCODE SIGNAL
  - 5 DECODE SIGNAL
  - 6 ENCODE OFFSET
  - 7 DECODE OFFSET
  - 8 D/A FILTER OUT/PHASE INVERT
  - 9 OUTPUT SIGNAL
  - 10 -15V
  - 11 +15V
  - 12 +5V
  - 13 GROUND
  - 14 LFO/CV
  - 15 CLOCK
  - 16 DATA OUT (RAM)



<http://www.adadepot.com>