

Table of Hotkeys Listed in Alphabetical Order.

<u>Command</u>	<u>Hot Key</u>	<u>EZ-Route</u>	<u>EZ-Logic</u>	<u>EZ-Symbol</u>	<u>EZ-Board</u>	<u>EZ-View</u>
About	H	X	X	X	X	X
Absolute/Local	“.”				X	X
Add Part by Library	A		X			
Add Part by Name	J		X			
Arc	A				X	
Back Annotate	K		X			
Bus	B		X			
Component Ref.	N				X	
Copy	C		X		X	
Cut	Shift + DEL		X		X	
Delete	DEL		X	X	X	
Design Check	D		X			
DOS Shell	D	X				
Exit	ALT + X	X	X	X	X	X
Flat/Component	Space Bar				X	
Formal Reports	Y		X			
Format	E		X		X	
Freshen	F		X			
Grid/Cursor	G		X		X	
Hierarchy Pop	-		X			
Hierarchy Push	+		X			
Insert	Ctrl + Enter			X		
Layers/Masks	M				X	
Line	L		X		X	
Load Symbol	Ctrl + L				X	
Locate	K				X	
Net name	N		X			
New	Ctrl + N		X		X	
Open	Ctrl + O		X		X	X
Pad	P				X	

<u>Command</u>	<u>Hot Key</u>	<u>EZ-Route</u>	<u>EZ-Logic</u>	<u>EZ-Symbol</u>	<u>EZ-Board</u>	<u>EZ-View</u>
Pan Center	Shift + Num 5		X		X	X
Pan Down	PgDn		X	X	X	X
Pan Left	<		X	X	X	X
Pan Right	>		X	X	X	X
Pan Up	PgUp		X	X	X	X
Paste	Shift + INS		X		X	
Point	F4				X	
Port	P		X			
Print	Ctrl + P		X		X	
Redraw	Ctrl + R		X	X	X	X
Region Pour	R				X	
Save	Ctrl + S		X		X	
Save As	Ctrl + A		X		X	
Save Symbol	Ctrl + V				X	
Select	S		X		X	
Select Trace	R		X			
Setup Printer	I		X		X	X
Sheet	V		X			
Show Options	M					X
Snap to Pad	F					
Solid Area	D				X	
Status	Q		X			
Text	T		X		X	
Toggle Layer	F9				X	
Undo	F2		X	X	X	
Unselect	Z		X		X	
Update	U		X		X	
Void Area	V				X	
Wire	W		X			
Zoom End	Ctrl + End		X	X	X	X
Zoom Home	Ctrl + Home		X	X	X	X
Zoom In	Ctrl + PgUp		X	X	X	X
Zoom Out	Ctrl + PgDn		X	X	X	X