

SONY

**Dictation Products
Service Bulletin**

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CCP-200 RF/D

No.12

Subject: Reformat Board Availability

Date: February 19, 1992

Symptom:
(**)

The mounted reformat board is now available from the National Parts Center.

Solution:

When ordering the board, please use the following part number:

DESCRIPTION	PART NUMBER
MCB, REFORMAT	T-9985-467-1

The same board is included in the FRB Program. Please contact the following for a FRB exchange:

Sony Service Company
11712 West 95th St.
Overlook Park, KS 66214
Tele. (913) 888-2622

CSA-15 Court Conference

Reference: Y.K.

PRINTED IN U.S.A.
CSA-15292-3