

SONY

Dictation Products Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CCP-200 RF/D

No.13

Subject: Part Numbers for the Replacement Heads
and Associated Parts

Date: February 19, 1992


Symptom:
(**)

The part numbers for the replacement heads and associated parts for the CCP-200 RF/D are not listed in the Service Manual.

Solution:

Please add the following part numbers to your Service Manual:

DESCRIPTION	PART NUMBER
HEXALLOY HEAD, RECORD	1-543-801-11
HEXALLOY HEAD, PLAYBACK	1-543-802-11
BASE ASS'Y, HEAD	X-3162-336-1
SPACER	3-162-422-01
PLATE, SHIELD, HEAD	3-164-213-01



CAUTION: When removing Chassis Ass'y, Head, pay special attention not to lose the three rollers (3-558-448-00) and the three steel balls (7-671-154-01)

Reference: Y.K.

PRINTED IN U.S.A.
CSA-15292-4

CSA-15 Court/Conference