



PARTS DESCRIPTION:

TL022C LOW POWER DUAL OPAMP; (TEXAS INSTRUMENTS)  
 MN3101 CLOCK GENERATOR FOR BUCKET BRIGADE DEVICE /BBD  
 (5.12-51.2 msec delay)  
 MN3007 AUDIO SIGNAL DELAY, 1024 STAGE LOW NOISE BBD  
 (5.12-51.2 msec delay)  
 CD4007 DUAL COMPLEMENTARY PAIR WITH INVERTER; (RCA)  
 MN3101/MN3007 MANF. PANASONIC; THESE ARE EQUIVALENT  
 TO EC61639/EC61641 RESPECTFULLY.

A COMMON POINT (OR JUNCTION) IS ILLUSTRATED BY >>  
 WHEN THIS IS NOT SEEN, WIRES WHICH CROSS OVER EACH  
 OTHER ON THIS SCHEMATIC ARE "NOT" CONNECTED.

Title		
DOD FX75 FLANGER (10-15-84)		
Size	Document Number	REV
B	DRAWN BY: FABIAN P. HARTERY	1
Date:	November 20, 1994	Sheet 1 of 1