

SONY

Dictation Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: DTI-800

No. 19

Subject: MCB, Complete

Date: October 16, 1992

Symptom:
(**)

The mounted board is now covered under the FRB Parts Exchange Program.

FRB P/N	DESCRIPTION	SUGG. LIST	EXCHANGE
T-9985-502-1	MCB, COMPLETE	\$ 350.00	\$ 100.00

Solution:

Please contact the following for exchange:

Sony Service Company
11712 W. 95th Street
Overland Park, Kansas 66214
Telephone (913) 888-2622

For the detailed procedure, please refer to the 1992 Business Products Dealer Service Policy, Section DP9, FRB Parts Exchange Program.

CSA-15 Dictation

Reference: YK

PRINTED IN U.S.A.
CSA-151092-3